



TECH TIP

Product: FCB - VIPER

Subject: EXPANSION TANK

Date: JANUARY 16, 2015

Description of Potential Issue:

Through normal operation of the Viper unit, the expansion tank may experience leaks or a rupture of the bladder inside of the expansion tank. This may cause product to back-feed out of the freeze cylinder into the CO2 lines and through the vent hole of the regulator.

Corrective Action:

A kit has been developed, **P/N 629097390**, that will convert to an improved version FloJet expansion tank. One kit will convert one barrel of the Viper unit. Please use the instructions enclosed with the kit, **P/N 629097390INS**, for a step by step guide to install the new expansion tank.

This improved expansion tank will fit all existing model Viper units. As this is a standard product enhancement, standard warranty coverage will apply to the kit installation.

Additional Information:

CAUTION

Only trained and certified electrical, plumbing and refrigeration technicians should service this unit. **ALL WIRING AND PLUMBING MUST CONFORM TO NATIONAL AND LOCAL CODES. FAILURE TO COMPLY COULD RESULT IN SERIOUS INJURY**

WARNING

Disconnect all power to the unit before performing any service. **VERIFY ALL POWER IS OFF TO THE UNIT BEFORE ANY WORK IS PERFORMED. FAILURE TO DISCONNECT THE POWER COULD RESULT IN EQUIPMENT DAMAGE, SERIOUS INJURY, OR DEATH.**