



**MARMON**  
Foodservice  
Technologies

A BERKSHIRE HATHAWAY COMPANY

## TECHNICAL SERVICE BULLETIN

**Product:** Cornelius Viper and Viper Elite  
**Subject:** Freeze Barrel Black Rear Seals  
**Date:** 10/12/2021  
**Cornelius Part Number:** 620043064

Dear Valued Partners and Customers,

We would like to announce that the Viper rear freeze **black** barrel seal is now rated for 12 months of service use (instead of being previously rated for 6 months). The seal will be required to be replaced during the factory recommended **annual** Scheduled Preventive Maintenance.

Cornelius Viper manuals have been updated to reflect the change to the 12-month replacement schedule. The gaged O-ring used in the motorman valve (Part Number 2818), if equipped on the Viper, must still be replaced every 6 months for proper operation.

Replacement black seals may be ordered directly from Marmon Link at <https://www.marmonlink.com/>

Seal replacement Video at [www.cornelius.com](http://www.cornelius.com)  
<https://vimeo.com/141924212>

Sincerely,

Cornelius Frozen Team



©2021, Marmon Foodservice Technologies  
Condenser\_Fan\_2021\_Viper\_TSB4 [www.cornelius.com](http://www.cornelius.com)



ANGELOPO



PRINCECASTLE



SILVERKING



MARMON RENEW

SAGI



Display Technologies  
Innovative Merchandising Solutions